FIM FORNITURE INDUSTRIALI MORDENTI SRL

ART	Ø"	1/4	3/8	1/2	3/4	ī	1%	11/2	2	21/2	3	4	5	6	8
ANI	DN	8	10	15	20	25	32	40	50	65	80	100	125	150	200

VALVOLA A SFERA PER ACQUA E RISCALDAMENTO BALL VALVES FOR HEATING AND WATER PLANTS

2	PN	32	32	32	32	32	25	25	20	16	16	16			
	€														
1	В□Х	30	30	20	15	10	6	3	2	-	-	-			
20	PN	32	32	32	32	32									
4	€														
	вох	40	30	30	15	10									
21	PN			32	32	32	25	25	20						
	€														
	BOX			20	15	10	5	3	2						
211	PN			32	32	32									
-	€														
4	BOX			20	15	10	70.0								
4	PN	20	20	20	20	20	16	16	16	10	10	10			
	€							_	-						
40	BOX	30	30	20	15	10	10	5	2	-	-	-			
40	PN	32	32	32	32	32									
40	€	10	30	20	20	10									
	BOX	40	30	30	20	10	14	17	17						
73	PN	20	20	20	20	20	16	16	16	10	10	10			
200	€ BOX	30	30	20	15	10	10	5	3						\vdash
450	PN	20	20	20	20	20	70	3	3	-	-	-			
130	€	20	20	20	20	20									
	вох	40	30	30	20	10									\vdash
46	PN	20	20	20	20	20	16	16	16						
	€														
	вох	30	30	20	15	10	10	5	3						
45 I	PN	20	20	20	20	20									
	€														
	вох	40	30	30	15	10									
19	PN		20	20	20	20	16	16	16						
	€														
Carlo da	вох		30	25	15	10	10	3	2						
190	PΝ		20	20	20	20									
	€														
A	вох		30	25	15	10									
6	PN	32	32	25	25	25	20	20	20	10	10	10			
-	€														
The same	вах	30	30	20	15	10	10	5	2	-	-	-			
60	PN	32	32	25	25	25									
-	€				<u> </u>				-			l	<u> </u>		
The same	BOX	40	30	30	20	10									
A DT	Ø"	1/4	3/8	1/2	3/4	1	1%	11/2	2	21/2	3	4	5	6	8
ART	DN	8	10	15	20	25	32	40	50	65	80	100	125	150	200

	ø"	1/4	3/8	1/2	3/4	1	1%	11/2	2	21/2	3	4	5	6	8
ART	DN	8	10	15	20	25	32	40	50	65	80	100	125	150	200
6 I	PN		32	25	25	25	20	20	20	16	16	16			
	€														
EL	вах		30	20	15	10	9	3	2	-	-	-			
610	PN		32	25	25	25									
	€														
	вох		30	30	15	10									
65	PN			25	25	25	20	20	20						
-	€														
	BOX			20	12	12	10	5	2						
65 _{RU}	PN			25	25	25	20	20	20						
	€			20		/2	10	-	_						
3	BOX PN	20	20	20	12 20	12	16	5	2 16		10	10	10	10	
3	€	20	20	20	20	20	10	16	10	10	10	10	10	10	
	вох	30	30	30	20	20	12	10	3	2	-	-	-	-	
30	PN	20	20	20	20	20	,_	, ,		-					
	€														
A TO	вох	40	30	40	30	15									
620	PN			20	20	16	16								
-	€				1 30 1 30 30										
	вах			20	10	10	6								
62 I	PN			20	20	16									
	€														
	вах			20	10	10									
45R	PN								16						
	€								-						
40	BOX				0.250				3						
48	PN			20	20	20	20	20	20						
-	€ BOX			30	20	10	6	6	4						
150	PN														
30	€			25	25	25	20	20	20						
100 110	вох			25	20	12	-	-	-						
151	PN			25	25	25	20	20	20						
2	€														
Sale In	вох			25	20	12	-	-	7_						
18	PN					16									
-36	€														
Annual	вох					10									
I8 _{NR}						16									
-	€					0.00									
40	вох					10									
68 <u>.</u>	PN			25	25	25	20	20	20						
	€ BOX			20	15	10	10	5	2						
681	PN			25	25	25	20	20	20						
4	€			10	10	10	20	10	20						
1	вох			20	15	10	10	5	2						
	Ø"	1/4	3/8	1/2	3/4	ı	11/4	11/2	2	21/2	3	4	5	6	8
ART	DN	8	10	15	20	25	32	40	50	65	80	100	125	150	200
	,														

	ø"	1/4	3/8	1/2	3/4	ı	1¼	11/2	2	21/2	3	4	5	6	8
ART	DN	8	10	15	20	25	32	40	50	65	80	100	125	150	200
69	PN			25	25	25	20	20	20						
	€														
	вох			20	15	10	10	5	2						
69 I	PN			25	25	25	20	20	20						
	€														
	вох			20	15	10	10	5	2						
9LV	PΝ	40	40	32	25	25	16	16	16						
	€						•			•		•			
11/0	вох	7	6	5	4	3	2	-							
9TV	PΝ	40	40	32	25	25	16	16	16						
	€														
11/4	вох	7	6	5	4	3	2	-	-						
7	PN			20	20	20									
4	€														
	вох			10	5	5									
70	PΝ			20	20	20									
	€														
	вох			8	6	5									
71	PN			20	20	20									
2	€														
0	вох			6	5	4									
72	PN			20	20										
4	€														
	вох			-	i										
73	PN			20	20										
	€														
686	вох			-	-										
74	PN			20	20										
-	€														
	вох			-	-										
75	PN			20	20										
I	€														
	вох			-	-										
519s				10											
	€														
FLOG	вох			100											
519G				10											
	€														
Q	BOX			100											
8	PN	10	10	10											
TI	€														
QI	BOX	75	75	50											
81	PN	10	10	10											
THE	€ BOX	75	75	50											
82	PN	/5	/5	50 10											
	€			10											
-4-	€ BOX			125											
	Ø"	1/4	3/8	1/2	3/4	ı	1%	11/2	2	21/2	3	4	5	6	8
ART	\vdash														
	DN	8	10	15	20	25	32	40	50	65	80	100	125	150	200

FIM FORNITURE INDUSTRIALI MORDENTI SRL E-MAIL fimmordenti @fimsrl.eu tel.0187 770873 fax 0187 770881

A DT	Ø"	1/4	3/8	1/2	3/4	ı	1%	11/2	2	21/2	3	4	5	6	8
ART	DN	8	10	15	20	25	32	40	50	65	80	100	125	150	200
83	PN			10											
1	€														
	вах			100											
606s	PN					10									
Ğ	€														
	вох					-									
16	PN				16	16	16	16	16	16	16	16	16	16	16
CA	€)
E	вах				-	-	-	-	-	-	-	-	-	-	-

VALVOLA A SFERA PER GAS BALL VALVES FOR GAS

										13					
17	PN		5	5	5	5	5	5	5						
-	€	'		•											
- Action	вох		25	20	15	10	-	-	-						
170	PN		5	5	5	5									
-	€														
- Andrews	вох		40	25	15	10									
187	PN		5	5	5	5	5	5	5						
	€	'													
and the same	вах		25	25	16	10	-	-	-						
187F	PN		5	5	5	5									
	€				_										
marks.	вах		25	25	16	10									
188	PN		5	5	5	5	5	5	5						
	€	·													
	BOX		25	25	16	10	-	-	-						
188F	PN		5	5	5	5									
	€	· ·													
	BOX		25	25	16	10									
7 _{FCS}	-			5	5	5	5	5	5						
_	€	·													
Die of Alle	BOX			-	-	-	-	-	-						
160	PN				16	16	16	16	16	16	16	16	16	16	16
ALE A	€														
117	вох				-	-	-	-	-	-	-	-	-	-	-
172	PN			0.07											
	-			8-37 mbar											
45	€			mbar											
	вах			mbar 30											
173	вах PN			mbar											
173	BOX PN €			30 8-37 mbar											
-	BOX PN € BOX			30 8-37 mbar											
173	BOX PN € BOX PN			30 8-37 mbar											
174	PN €			30 8-37 mbar 30 8-37 mbar											
174	BOX PN € BOX PN €			30 8-37 mbar 30 8-37 mbar											
174	BOX PN € BOX PN € PN FN			30 8-37 mbar 30 8-37 mbar											
174	BOX PN € BOX PN € PN €			30 8-37 mbar 30 8-37 mbar 30 8-37 mbar											
174	BOX PN BOX PN € BOX PN E BOX			30 8-37 mbar 30 8-37 mbar 30 8-37 mbar											
174	BOX PN € BOX PN € PN €	1/4	3/8	30 8-37 mbar 30 8-37 mbar 30 8-37 mbar	3/4		11/4	11/2	2	21/2	3	4	5	6	8
174	BOX PN BOX PN € BOX PN E BOX	1/4	3/8	30 8-37 mbar 30 8-37 mbar 30 8-37 mbar	3/4	I 25	11/4	11/2	2 50	21/2	3 80	4	5	6	8 200

176	DN	8													
176		•	10	15	20	25	32	40	50	65	80	100	125	150	200
and the same	PN			8-37 mbar											
- Allen	€														
and the latest designation of the latest des	вох			30											
177	PN			8-37											
· ` 🚋	€			mbar											
-	вох			30											
178	-			8-37											
170	PN			mbar											
-	€			-			<u> </u>					<u> </u>			
	вох			30 8-37											
179	PN			mbar											
-	€														
J	вох			30											
180	PN			8-37 mbar	8-37 mbar	8-37 mbar									
2	€			-											
	вох			30	30	30									
181	PN			8-37											
	€			mbar											
	вох			30											
182	\longrightarrow			8-37											
	PN			mbar											
	€											1			
w	вох			30	9.27										
183	PN			8-37 mbar	8-37 mbar										
The same of	€														
	вох			30	30										
184	PN			8-37 mbar	8-37 mbar										
S)	€			•		•	•					•			
	вох			30	30										
185	PN			8-37 mbar											
	€			mbar											
	вох			30											
186	PN			8-37 mbar											
-00	\longrightarrow			mbar											
-	€														
104	BOX			30 8-37	8-37										
18 6 ca	$\overline{}$			mbar	mbar										
-	€														
	вох			30	30										
195	PN			8-37 mbar											
	€					'	'								
	вох			30											
196	PN			8-37 mbar	8-37 mbar										
	€			IIIDar	IIIDar										
Samuel B	вох			30	30										
191м	PN		1	ı	50										
	\rightarrow		•	•											
A STATE OF THE PARTY OF THE PAR	€														
6	BOX		20	30											
191 _F	PN		- 1	- 1											
	€														
	вох		20	30											
ΛРΤ	Ø"	1/4	3/8	1/2	3/4	I	1%	11/2	2	21/2	3	4	5	6	8
ART	DΝ	8	10	15	20	25	32	40	50	65	80	100	125	150	200

6
150

SARACINESCHE IN OTTONE, BRONZO E GHISA BRASS, BRONZE AND CAST IRON GATE VALVES

ART	DN	8	10	15	20	25	32	40	50	65	80	90	100	125	150
A DT	Ø"	1/4	3/8	1/2	3/4	1	1%	11/2	2	21/2	3	31/2	4	5	6
170	вах		-	-	-	-	-	-	-	-	-		-		
=/	€														
245	PN		10	10	10	10	10	10	10	6	6		6		
	вах			10	10	10									
	€														
240	PN			16	16	16									
A	вах			20	10	10	10	5	5						
•	€			10	10	10	10	10	10						
230	PN		20	16	16	16	16	16	16						
ě.	€ BOX		20	20	20	10	20	20	10						
226	PN		12 mm	15 mm	18 mm	22 mm	28 mm	35 mm	42 mm						
224	BOX		16	20 16	20 16	10	16	16	16						
I	€														
225	PN			16 15 mm	16 22 mm	16 28 mm									
	вах	20	20	20	20	20	10	10	5	5	-		-		
7	€														
220	PN	10	10	10	10	10	10	10	10	10	10		10		
	вах	20	20	20	20	10	10	5	5	-	-	-	-	-	-
	€														
215	PN	16	16	16	16	16	16	16	16	16	16	16	16	16	16
*	вох	20	20	20	20	10	10	5	5	-	_		-		
~	€	20	20	20	20	20	20	20	20	20	20		20		
205	PN	20	20	20	20	20	20	20	20	20	20		20		
A	€ BOX			20	20	20	10	10							
212	PN			16	16	16	16	16							
212	BOX	20	20	20	20	10	10	5	5	-	-		-	-	-
A	€							_							
210	PN	16	16	16	16	16	16	16	16	16	16		16	16	16
400	вах		-	-	-	-	-	-	-	-	-		-		
T	€														
200	PN	25	25	25	25	25	25	25	25	25	25		25		

	ø"	1/4	3/8	1/2	3/4	ı	1%	11/2	2	21/2	3	4	5	6	8
ART	0	1/4	3/0	1/2	3/4	'	174	172		272		4	3	•	•
	DN	8	10	15	20	25	32	40	50	65	80	100	125	150	200
255	PN					16	16								
I	€														
10	вох					14	5								
D26	PN					16	16								
I	€														
620	вох					10	6								
D27	PN					16									
I	€														
600	вох					10									
260	PN			16	16	16	16	16	16	16	16	16			
150	€														
	вох			-	-	-	-	-	-	-	-	-			
265	PN							10	10	10	10	10	10	10	10
A	€)
(100)	вох							-	-	-	-	-	-	-	-
266	PN							16	16	16	16	16	16	16	16
. &	€)
(100	вох							-	-	-	-	-	-	-	-
265cc	-							16	16	16	16	16	16	16	16
	€				<u> </u>			_	_		-	_	-		
Dark.	вох							-	-	-	-	-	-	-	-
267	PN							16	16	16	16	16	16	16	16
	€			<u> </u>	<u> </u>										
9	вох							-	-	-	-	-	-	-	-
268	PN							16	16	16	16	16	16	16	16
	€				<u> </u>			-	-	-	_	-	-	-	_
30%	вох							-	-	-	-	-	-	-	-

FILTRI IN OTTONE, BRONZO E GHISA BRASS, BRONZE AND CAST IRON FILTERS

411	PN		20	20	20	20	20	20	20	16	16	16			
The same	€														
	вох		25	20	12	10	10	5	2	-	-	-			
412	PN	20	20	20	20	20	20	20	20	16	16				
	€														
	вох	20	20	20	20	10	10	5	2		-				
412r	PN					20									
	€														
	вох					20									
413	PN	6	6	6	6	6	6	6	6						
	€														
	вох	20	20	20	20	10	10	5	2						
415	PΝ			16	16	16	16	16	16	16	16	16	16	16	16
	€											_		_	
1	вох			-	-	-	-	-	-	-	-	-	-	-	-
416	PN				10										
1 House	€							-							
	вох				10										
A DT	Ø"	1/4	3/8	1/2	3/4	1	1¼	1½	2	21/2	3	4	5	6	8
ART	DΝ	8	10	15	20	25	32	40	50	65	80	100	125	150	200

A DT	ø"	1/4	3/8	1/2	3/4	1	1%	11/2	2	21/2	3	4	5	6	8
ANI	DN	8	10	15	20	25	32	40	50	65	80	100	125	150	200

VALVOLE IN OTTONE E BRONZO BRASS AND BRONZE VALVES

410	DNI			1.0	17	1.0	1.0	1.0	17					
410	PN			16	16	16	16	16	16	10	10	10		
	€													
4	вох			-	-	-	-	-	-	-	-	-		
410A	PN			16	16	16	16	16	16	10	10	10		
	€			-	-	-	-	-	-		-	-	-	
Sealer .	BOX			-	-	-	-	-	-	-	-	-		
417	PN			20	20	20	20	20	20	20	20			
I	€			-	-	-	-	-	-	-	-			
Service .	BOX			-	-	-	-	-	-	-	-			
419	PN			16	16	16	16	16	16					
	€				_	_	_	-	_					
	вох			-	-	-	-	-	-					
421	PN	16	16	16	16	16	16	16	16	16	16	16		
4	€													
	вох	-	-	-	-	-	-	-	-	-	-	-		
42 Ism	PN	16	16	16	16	16	16	16	16	16	16	16		
4	€													
	вох	-	-	-	-	-	-	-	-	_	-	-		
422	PN	16	16	16	16	16	16	16	16	16	16			
-	€													
-	вох	-	-	-	-	-	-	-	-	-	-			
424	PN	10	10	10										
	€													
	вох	-	_	-										
424s	PN	25	25	25								1		
4245	-	23	23	23										
5	€ BOX													
F40	_	-	-	-										
560	PN		12	12	12	12	12	12	12	12	12			
A.	€													
F 70	BOX		-	-	-	-	-	-	-	-	-			
570	PN		12	12	12	12	12	12	12					
	€													
**	вох		-	-	-	-	-	-	-					
600	PN			10	10	10	10	10	10	10	10	10		
N. Y	€													
	вох			-	-	-	-	-	-	-	-	-		
606	PN				16	16	16							
10	€													
-4	вох				-	-	-							
		١ / ٨	1110) F		_ \	101	DIT		10 [DET	

VALVOLE DI FONDO, NON RITORNO E CLAPET FOOT VALVES AND NON RETURN VALVES

400	PN			10	10	10	10	10	10	10	10	10			
40.3	€														
	BOX			20	12	10	10	6	4	-	-	-			
ART	Ø"	1/4	3/8	1/2	3/4	1	11/4	11/2	2	21/2	3	4	5	6	8
	DΝ	8	10	15	20	25	32	40	50	65	80	100	125	150	200

	Ø"	3/8	1/2	3/4	ı	1%	11/2	2	21/2	3	4	5	6	8	10
ART	DN	10	15	20	25	32	40	50	65	80	100	125	150	200	250
401	PN		10	10	10	10	10	10	10	10	10				
400	`€														
(d	вох		25	12	10	10	6	4	-	-					
465	PN						16	16	16	16	16	16	16	16	
A PER	€														
-	вох						-	-	-	-	-	-	-	-	
420	PN		10	10	10	10	10	10	10	10	10	10			
	€														
ini	вох		25	20	15	15	10	5	-	-	-	-			
420 _G	PN							16	16	16	16	16	16	16	16
1	€										-		-		
	вох							-	-	-	-	-	-	-	-
430	PN			10	10	10	10	10	6	6	6				
	€			-	-	-	-	-	-	-	_				
	вох			20	15	10	10	5	-	-	-				
460	PN				10	10	10	10							
	€		-		-	-	-	-		-	-		-	-	
170	BOX				-	-	-	-							
470	PN	20	20	20	20	16	16	16	10	10	10				
	€			-				-							
475	BOX	10	10	8	6	4	4	2	-	-	-				
4/3	PN	20	20	20	20	16	16	16	10	10	10				
	€	_		,		,	2	-							
480	BOX	8	8	6	4	4	2	2	-	-	-				
400	PN €	16	16	16	16	10	10	10	6	6	6				
	вох	-	-	-	-	-	-	-	-	-	-				
480 _{GF}			_	_	-	-	-	16	16	16	16	16	16	16	
Aug	€										10	10			
VIE	вох							-	-	-	-	-	-	-	
477	PN			10	10	10	10	10							
1	€														
100	вох			-	-	-	-	-							
485	PN	-	-	-	-	-	-	-	-	-	-				
	€														
	вох	50	50	50	25	20	15	10	-	-	-				
			DI ID	SINE) A C	DEC.	TOI		EDO	$C\Lambda$	71/01/	IE		
				STOP(NC		
205	I ¹								4D D/	VET DI		-1/-0			
305	PN	10	10	10	10	10	10	10							
4	€														
215	BOX	20	20	10	10	-	-	-							
315	PN		10	10	10										
T	€		10	-	-										
84	BOX		10	5	5										
	PN		10	10	10										
	€ BOX		12	10	5										
Ψ	+								,						,,,,,,,,
	Ø"	3/8	1/2	3/4	1	11/4	11/2	2	21/2	3	4	5	6	8	10

FIM FORNITURE INDUSTRIALI MORDENTI SRL E-MAIL fimmordenti @fimsrl.eu tel.0187 770873 fax 0187 770881

	ø"	1/4	3/8	1/2	3/4	ı	1%	11/2	2	21/2	3	4	5	6	8
ART	\vdash														
	DN	8	10	15	20	25	32	40	50	65	80	100	125	150	200
440 *	PN			10	10	10									
1	€			<u> </u>						<u> </u>					
-	BOX			10	10	10									
445	PN				10	10	10	10	10						
The state of the s	€											·			
- 8	вох				-	-	-	-	-						
5	PN			10	10	10									
	€											<u> </u>	<u> </u>	<u> </u>	
T	BOX			20	10	5									
35	PN		10	10	10	10									
55	€		2-			,-									
T	BOX		20	20	10	10									
56	PN			10											
-	€									l					
FOO	BOX			20											
520	PN			20	20										
1	€									l					
FOE	BOX			-	-										
525	PN			10	10										
4	€														
ESE	BOX			15	10										
535	PN		10	10	10	10									
	€ BCX			10		-									
<u>7</u> 545	-		15	10	10	5									
343	PN €		10	10	10										
T	€ BCX		1E	10	10										
521	PN		15	10	10										
J	€			10											
	€ BOX			12											
528	PN			10											
J 20	€			10											
	€ BOX														
•		D. 15		- 		C C !		D:-			<u> </u>	DESS			

RUBINETTI A MASCHIO - RIDUTTORI DI PRESSIONE PLUG COCKS - PRESSURE REDUCERS

500	PN			10	10	10	10	10	10	10	10	10			
	€														
	вах			30	15	10	-	-	-	-	-	-			
505	PN				10	10	10								
- Alle	€				_										
	вах				15	10	-								
506	PN			10											
	€														
44	вах			12											
507	PN			10											
	€														
	вах			12											
	ø"	1/4	3/8	1/2	3/4	ı	11/4	11/2	2	21/2	3	4	5	6	8
ART	DΝ	8	10	15	20	25	32	40	50	65	80	100	125	150	200


	Ø"	1/4	3/8	1/2	3/4	ı	1%	11/2	2	21/2	3	4	5	6	8
ART	DN	8	10	15	20	25	32	40	50	65	80	100	125	150	200
510	PN		16	16	16	16	10	10	10	10	10				
-	€														
	вох		-	-	-	-	-	-	-	-	-				
518	PN			10	10	10	10	10	10						
- Miller	€			_	_	-		_							
	BOX			12	10	5	-	-	-						
519	PN			10											
-	€														
	вох			100											
516	PN				1			1	1.	1	1	- 1			
-	€														
~	вох				-			-	-	-	-	-			
60 I	PN			10	10										
A.	€							<u> </u>			—			 	
T	BOX			1	1										
602ap	-			25											
offe	€						 				—			 	
	BOX			1											
602	PN			20	20	20	20	20	20						
offe	€			,	-	,		_	-	 					
611	BOX			1	1	1	-	-	-		- 20				
□	PN			20	20	20	20	20	20	20	20				
-	€ BOX														
590	PN	6	6	6	-	-	-	-		-	-				
	€	•	•		<u> </u>										
	вох	-	-	-											
59 I	PN		6	6											
1	€														
	вох		-	-											
592	PN		6	6											
-	€														
1	вох		_	-											
595	PN		6	6											
	€														
1	вох		-	-											
										ILI E			ΤI		
			F	TITTIN	GS FC	or fl	EXIBL	E ANI	D THI	READ	ED PI	PES			
603	PN		10	10	10	10	10	10	10						
	€														
	вох		-	-	-	-	-	-							
604	PN		10	10	10	10	10	10	10						
MIDW	€														
980	вох		-	-	-	-	-	-	-						
605	PN					16									
	€														
	вох					-									
	ø"	1/4	3/8	1/2	3/4	ı	1¼	11/2	2	21/2	3	4	5	6	8
ART	\rightarrow									$\overline{}$					

 ${\it FIM}\ FORNITURE\ INDUSTRIALI\ MORDENTI\ SRL\ E-MAIL\ fimmordenti\ @\ fimsrl.eu\ tel. 0187\ 770873\ fax\ 0187\ 770881$


605L	-					- 1									
	€														
-	BOX					-									
612	Ø"			1/2 X 3/4	3/4 X I										
STATE OF	€														
0	вох			-	-										
850	Ø"	3/8 X 15	1/2 X 15	1/2 X 18	I/2 X 20	3/4 X 20	3/4 X 25	1 X 25	I X 30	I X 32	1¼ X 30	1% X 32	1% X 35	1½ X 40	2 X 50
	€														
	вох	25	25	15	15	15	15	15	10	10	10	10	8	6	6
	Ø"	2 X 60	2½ X 60												
	€		_												
	вох	5	5												
85 I	Ø"	3/8 X 15	1/2 X 15	1/2 X 18	1/2 X 20	3/4 X 20	3/4 X 25	I X 25	I X 30	1¼ X 30	1% X 35	1½ X 40	2 X 50	2 X 60	2½ X 60
E PAR	€														-
	вох	20	20	10	10	10	15	12	8	8	5	4	5	3	3
852	Ø	15	18	20	25	30									
	€														
The same	вох	25	15	15	20	10									
853	Ø"	1/8 X 6	1/8 X 8	1/8 X 10	1/4 X 6	1/4 X 8	1/4 X 10	1/4 X 13	3/8 X 10	3/8 X 13	3/8 X 15	1/2 X 10	1/2 X 13	1/2 X 15	1/2 X 16
	€														
	вох	50	50	50	50	50	50	50	40	30	30	50	50	50	50
'	Ø"	1/2 X 18	1/2 X 20	3/4 X 13	3/4 X 16	3/4 X 18	3/4 X 20	3/4 X 22	3/4 X 25	I X 20	1 X 25	1 X 27	1 X 30	I X 32	1% X 30
	€	1													Į.
	вох	40	40	30	30	30	25	25	20	30	30	30	25	25	20
1 1	Ø"	1% X 32	1% X 35	1¼ X 39	1% X 40	1½ X 38	1½ X 40	1½ X 45	1½ X 50	2 X 50	2 X 51	2 X 60	2½ X 60	2½ X 63	2½ X 70
	€														
	вох	20	15	15	15	15	12	10	10	8	8	5	8	8	5
\	Ø"	3 X 76	3 X 80	4 X 100	4 X 102	A 10					0.52				
	€														
	BOX	5	5	2	2										
854	Ø"	1/8 X 8	1/8 X 10	1/4 X 10	1/4 X 13	3/8 X 10	3/8 X 13	3/8 X 15	1/2 X 10	1/2 X 13	1/2 X 15	1/2 X 18	3/4 X 20	3/4 X 25	1 X 25
	€														
	вох	50	50	50	50	40	30	30	50	50	50	40	25	20	30
	Ø"	1 X 30	1% X 30	1¼ X 32	1% X 35	1½ X 40	2 X 50								
	€														
	вох	25	20	20	15	12	6								
855	Ø"			1/2	3/4	I	1%	11/2	2						
4	€														
	вох			20	15	8	5	4	3						
856	Ø"			1/2	3/4	- 1			<i>H</i> = 2						
	-														
	€														
*	€ _{BOX}			20	15	8									
1	-	1/4	3/8	20	15 3/4	8	1 1/4	1 1/2	2						
960	вох Ø"	1/4	3/8				1 1/4	I ½	2						
1	вох	1/4	3/8				1 1/4	1 1/2	2						
960	80× Ø" € 80×	_	-	1/2	3/4	I .			10						
***	BOX Ø" € BOX Ø"	_	25	30	3/4	12	12	10							
960	80× Ø" € 80×	_	25	30	20	12	12	10	10						
960	BOX Ø" € BOX Ø" € BOX	40	25 3/8 - 40	30 1/2	20 3/4	12 1	12	10	10						
960	BOX Ø" € BOX Ø" € BOX	40	25 3/8 - 40	30	20 3/4	12 1	12	10	10						
960	BOX Ø" € BOX Ø" € BOX	40	25 3/8 - 40	30 1/2	20 3/4	12 1	12	10	10						

980	Ø"		M 3/6 A	M 1/2 X 3/4	M 3/4 X I									
	€													
	вах		30	20	10									
98 I_	Ø"	3/8 X 12	3/8 X 15	3/8 X 20	3/8 X 30	3/8 X 40	3/8 X 50							
	€													
	вах	30	30	30	20	15	15							
	Ø"	1/2 X 12	1/2 X 15	1/2 X 20	1/2 X 25	1/2 X 30	1/2 X 40	1/2 X 50	1/2 X 60	1/2 X 80	1/2 X 100			
	€	_	-				-	-	_	_				
	вах	25	20	20	15	15	10	10	10	10	10			
	Ø"	3/4 X 12	3/4 X 15	3/4 X 20	3/4 X 30	3/4 X 40	3/4 X 50							
	€													
	вах	20	15	10	10	10	10							
	Ø"	1 X 12	I X 15	I X 20	I X 30	I X 40	I X 50							
	€													
	вах	20	20	15	10	10	10							
982	Ø"	1/2 X 60	I/2 X 80	1/2 X 100	1/2 X 120	1/2 X 150			3/4 X 60	3/4 X 80	3/4 X 100	3/4 X 120	3/4 X 150	
	€													
	вах	15	10	8	8	8			10	8	6	6	6	
	Ø"	I X 60	I X 80	I X 100	I X 120	I X 150								
	€													
	вах	10	10	6	6	4								
983	Ø"	1/2 X 1/2	3/4 X 3/4											
THE P	€													
	вах	15	20											

RUBINETTI SOTTOLAVABO IN OTTONE CROMATO C.P. BRASS UNDER-WASH BASIN TAPS



ACCESSORI E RICAMBI SPARE PARTS



A04						700				I	7-1			
AU4	Ø	1/4	3/8	1/2	3/4	ı	1%	11/2	2	21/2	3	4		
1	€													
	вох													
A05	Ø	1/4	3/8	1/2	3/4	- 1	1%	11/2	2	21/2	3	4		
	€											'		
Carrier.	вох													
AI3	Ø	1/4	3/8	1/2	3/4	- 1	1%	11/2	2	21/2	3	4		
to D	€													
	вох			_										
AI2	Ø	1/4	3/8	1/2	3/4	1	1%	11/2	2	21/2	3	4		
_	€		0.0	2	0,1	-	174	.,,	_	-/-				
IAB	BOX					,						 		
A15		1/4	2/0	1.10	214		11/	11/	_	21/	_			
A13	Ø	1/4	3/8	1/2	3/4	ı	1%	11/2	2	21/2	3	4		
100	€													
80/	BOX													
A06	Ø	1/4	3/8	1/2	3/4	ı	1%	11/2	2	21/2	3	4		
	€													
	вох													
A07	mis	I*	2*	3*	4*									
	€													
	вох													
A08	mis	I*	2*	3*	4°									
100	€			-			-			-			-	
	вох													
AQ9	Ø	1/4	3/8	1/2	3/4	1	1%	11/2	2	21/2	3	4		
	€													
The same	вох													
250	Ø	1/4	3/8	1/2	3/4	ı	1%	11/2	2	21/2	3	4		
A.	€		0.0	2	0,1	•	1,74	1/1	_			-		
	вох													
AÎ0		1/4	210	1/2	214		11/	11/	-	21/	-	_		
410	Ø	1/4	3/8	1/2	3/4	I	1¼	11/2	2	21/2	3	4		
	€													
	вох													
AI4	Ø	1/4	3/8	1/2	3/4	I	1%	11/2	2	21/2	3	4		
	€	-					 			_			<u> </u>	
9	BOX													
24A	Ø	1/4	3/8	1/2	3/4	I	1%	11/2	2	21/2	3	4		
	€													
	вох													
24P	Ø	1/4	3/8	1/2	3/4	ı	1%	11/2	2	21/2	3	4		
	€													
	вох													
3 I A	Ø	1/4	3/8	1/2	3/4	ı	1%	11/2	2	21/2	3	4		
A	€													
6	вох													
3 I P	Ø	1/4	3/8	1/2	3/4	ı	1%	11/2	2	21/2	3	4		
	€													
I	вох				•	•								
53A	Ø	1/4	3/8	1/2	3/4	ı	1%	11/2	2	21/2	3	4		
	-	17-4	3/0	172	3/4	•	174	1/2	-	4/1	,	-		
	€													
•	вох													

62A	Ø	1/4	3/8	1/2	3/4	- 1	1%	11/2	2	21/2	3	4		
027	\vdash	1/4	3/0	1/2	3/4	- 1	174	1 //2	4	472	3	4		
	€													
	вах													
23 T	Ø	1/4	3/8	1/2	3/4	- 1	1%	11/2	2	21/2	3	4		
	€												'	
	вох													
20A	Ø	45	50	55	60	70	80	100	120					
	€		-		_									
	вох													
4IR	Ø	1/4	3/8	1/2	3/4	- 1	1%	11/2	2	21/2	3	4		
	€						-							
	вох													
43R	Ø	1/4	3/8	1/2	3/4	- 1	11/4	11/2	2	21/2	3	4		
	€													
	вох													
54A	Ø	1/4	3/8	1/2	3/4	- 1	1%	11/2	2	21/2	3	4		
	€													
	вах													
606	Ø	1/4	3/8	1/2	3/4	1	11/4	11/2	2	21/2	3	4		
SRM 1	€					transit (* arrent								
	вах													

FIM FORNI

I prezzi si intendono I.V.A. esclusa