
# BROCHURE T SERIES

### **BIRAGHI POMPE 1906**





• SINCE 1906



**Centrifugal Tractor Driven Pumps** 



### T PROCESS PUMP


Our pumps for fresh water and sludge, linked to the tractor motor by shaft drive, are the simplest solution for delivering pressurized water to the rollers.


Our centrifugal pumps are designed to provide the ideal match between long-term service and immediate performance of irrigational activities.

TABELLA RAPPORTI POMPE CARRELLATE SERIE PM/T - RATIOS FOR PM/T SERIES TRACTOR PUMPS - TABLE DES RAPPORTS

Sigla rapporto Ratio type Rapport modéle	Pompa tipo Pump type Pompe modéle	Rapporto Ratio Rapport	N. denti Tooth - N.º Dents - N.º	Sigla rapporto Ratio type Rapport modéle	Pompa tipo Pump type Pompe modéle	Rapporto Ratio Rapport	N. denti Tooth - N.º Dents - N.º
A	T 25 T 50 T 100	1 : 5,71	80/14	F	T 100	1 : 4,87	78/16
В	T 25 T 50	1:6,25	81/13	G	T 25	1 : 4,53	77/17
С	T 25 T 50	1:6,83	82/12	*!	T 100	1:3,08	71/23
D	T 25	1:7,54	83/11	- *M	T 100	1:3,48	73/21
E	T 25 T 100	1:5,27	79/15	· *N	T 100	1:3,7	74/20

<sup>\*</sup>Solo per prese di forza a 1000 RPM - Only for 1000 RPM P.T.O. - Seulement pour price de force a 1000 TPM.





#### **APPLICATION**

To generally transfer clear or moderatly impure water, without chemical agents, up to 105 C:

- ⇒ Irrigation
- ⇒ Water lifting
- ⇒ Rain irrigation


### **OVERALL SIZES**

# VALORI INDICATIVI POMPE CARRELLATE SERIE PM/T - OVERALL DIMENSIONS FOR PM/T SERIES PUMPS DIMENSIONS D'ENCOMBREMENT ET POIDS

Tipo pompa Pump type Pompe modéle	A	В	С	D	E	F	G	н	1	L	м	N	O DN	Р	Q	R DN	s	T	U	v	Peso Weight Poids Kg.	Volume Volume Volume mc
PM2-3-4-/8 T25-1-2-3-4/80	449	401	265	180	85	120	148	13	83	96	200	160	80	18 Nº 4	190	65	145	185	18 N° 4	115	51	0,048
PM2-1/82 T25-1/802	536	418	300	180	85	120	148	13	83	183	200	160	80	18 N° 4	207	65	145	185	18 N° 4	115	70	0,0780
PM5-9 T50-90	529	495	297	235	112	130	179	14	87	108	200	160	80	18 N° 4	230	65	145	185	18 Nº 4	145	82	0,0787
PM5-10 - PM5-2/10 T50-10 - T50-2/100	535	515	341	235	112	130	179	14	87	114	220	180	100	18 Nº 8	250	80	160	200	18 Nº 4	145	85	0,0945
PM5-11 T50-110	536	495	310	235	112	130	179	14	87	115	220	180	100	18 N° 8	230	80	160	200	18 Nº 4	145	77	0,0824
PM5-2-4/82 T50-2-4/802	596	472	300	235	112	130	171	14	87	183	200	160	80	18 Nº 4	207	65	145	185	18 N° 4	145	94	0,096
PM10-1/12 - T100 1/125 PM10-2/12 - T100 2/125 PM10-3/12 - T100 3/125	539	530	384	235	112	130	179	14	87	118	250	210	125	18 N° 8	265	100	180	220	18 N° 8	145	98	0,110
PM2-11S T25-110S	472	396	277	180	85	120	155	13	83	112	220	180	100	18 Nº 8	185	100	180	220	18 Nº 8	115	58	0,0485
PM2-12S T25-120S	484	441	332	180	85	120	155	13	83	124	250	210	125	18 Nº 8	230	125	210	250	18 N° 8	115	61	0,050
PM5-12S T50-120S	550	495	332	235	112	130	184	14	87	124	250	210	125	18 Nº 8	230	125	210	250	18 N° 8	145	78	0,098

Capacitiy	to 300 m³/hr
Head	to 100 m
Max working pressure	to 10 bar
Temperature	to 50 C°

#### **OVERALL SIZES**



TIPO TYPE TYPE	DNa	DNm	А	В	C	D	ш	F	ט	н	_	-	Σ	z	0	۵.	Kg
50x200/1		1	260	130	323					ç			Ę		000		52
50x200/2	92	20	645	215	408	L	,	Ç	ç	790		100	<del>1</del>	211	700	1	67
65x250/1	20000	17.0	260	130	323	82	174	57	7	c c	717	200	46.1	- 17	050	2	63
65x250/2	08	65	645	215	408					320			401		730		88
80x250/1			645	165	373					020	5 55		212		250		95
80x250/2	90	<u>.</u>	755	275	483	;	133	ļ	Ş	0/6	330	325	0	390	007	772	127
100x250/1			645	165	373	711	132	۱۵	<u>+</u>	5	007	667	272	607	UBC	3	105
100x250/2	150	001	. 755	275	483					0 4	3		0+0		7007		135

### **OVERALL SIZES**

							JGAL GES PO						Z	T				ACTERIS		DE FONCTIONNEMENT  R.P.M. Tourymin						
883	TIPO	25.2	8	SI			,							PORT	ATA -	CAPAC	ITY - D	EBIT					L/mi	n.		
ASTATISCH.	TYPE	GRANTE THO IMPRIER THE ROLE THE	EMPORTO TIPO EUTO TIPE EMPORT TIPE	II.	200	300	400	500	600	700	800	900	1000	1100		1300	1400	*****	1800	2000	2250	2500			3500	400
523	TYPE	25.5	233	Ξ.	12	18	24	30	36	42	48	54	60	66	72	78	84	96'	108							
		с		н	67	65	62	58	54	48	42							100	- 1	- 1	- 1					
		٠	100	Р	9	10	11	11,8	12,5	13,2	14			1												
		Α.	x	н	81	81	80	77	73	68	61								-		-					
		^		Р	11	12,5	13,5	14,5	15,5	16,5	17,5											- 4				
	50x200/1	100	NPSH = n	t i	2,8	2,8	2,8	2,8	2,9	3,4	4,3															
	30,200,1	-		н	. 97	96	95	94	90	85	78							1	-	- 20	- 1	- 3	i.	la.		
		С	40	P	14,5	15,5	17	19	20	21	22											- 3	1			
			z	н	116	116	115	114	111	106	100									-		7 1	-	5		
•		Α.		P	18	20	22	24	25,5	26,8	28,2															
65 x 50			NPSH = n	t	4	- 4	4	4	4,1	4,2	4,7	3							70.00				-			
Š		D		н	130	127	124	118	109	99	88		-											7		
9		В		P	17,5	19	20,5	22	23,5	24,5	25,5		L						- 3		- 3					
		с		н	140	139	135	129	122	111	100				-											
		C	Y	P	20	22	24	25,5	27	28	28,5					- Aurona					lana (					
	50x200/2	В		н	150	148	145	139	131	121	108									9 8						
		В		Р	22	23,5	25	27	29	30	31															
		A		н	160	158	155	150	141	132	120	9 9														-
				Р	25	26,5	29	30,5	- 32	33	34		- i						1							
			NPSH = n		3,3	3,3	3,3	3,3	3,4	3,8	4,6	9						11 11 11	700	3.11.1.5						
		D		н				86	84	. 82	79	75	71	66	58	49	40			3 3						
		U		Р				19	20	21,5	23	25	26	27	28	28	28									
		с		н		-		98	97	95	93	90	87	83	78	71	62				1 1					
			x	Р				23	24,5	26	27,5	29	31	33	34	35	36									
	65x250/1	В	•	н				115	114	112	110	108	105	101	97	93	88									
	03,230,1	В		P				27,5	30	32	34	36	38	40	41,5	43	44,5									
		Α.		н				126	125	124	122	120	118	115	111	106	102			8 .						
9		0.00		Р				30,5	33,5	36	38,5	41	43	45	47	49	51									
80 x 65			NPSH = n	nt				3,2	3,2	3,2	3,3	3,4	3,6	3,9	4,2	4,6	5,1	100		100						
8		с		н				136	132	128	123	115	106	96	84				- 1	1						
		C		P			1	28	30,5	32,5	35	37,5	39	40	41											
		В	ĸ	н	1			149	146	142	137	130	122	113	103					1.00						
	65x250/2	В		P				34	36,5	39	41	43	44,5	45,5	46,5		1									
				н		1000000	5	159	156	152	148	141	134	126	115					3111	21 - 13					
		^		P				36,5	39	41,5	44	47	49	50	51	land in										
- 3			NPSH = n	d .	<u>.</u>	18,77,000	V 983	2,6	2,6	2,6	2,8	3	3,3	3,6	3,9	1	- 2			3 1	1		1			
04, 100g		с		н	14			1			73	73	72	71	70	69	67	63	57	51						
				Р							23	24	25	26	27	28	29	30	32							
		В	н	н							83	83	82	81	80	79	78	75	71	66	59					
				Р							27	28	29	30	31	33	35	37	39		-					
		Α.		н							94	94	93	93	92	91	90	87	84							
		3 2024		Р		-	200				32	33	34	36	38	40	42	44	46	48	51					
_	80x250/1		NPSH = n	-		1					2,4	2,5	2,6	2,7	2,8	2,9	3	3,4	3,9	4,5	5,2					
<b>~</b>		В		н							114	114	113	113	112	111	110	108	106	102	98					
×			x	Р		1 2					44	45	46	48	50	52	54	56	59	62	64					
100 x 80				н	1						127	127	127	126	126	125	124	122	120	116	112					
		1.46		P			-				49	50	52	54	56	58	60	64	68	71	74					
			NPSH = n								3,6	3,6	3,6	3,6	3,6	3,6	3,7	4	4,4	4,9	5,6					
		В		н							138	136	134	132	129	126	121	112	103	92	80					
			н	Р				-			43	45	47	49	51	53	55	57	60	63	66		Service			
	80x250/2	Α.		н							149	147	145	143	141	138	133	124	116	106	94					
		200,000		P		-		-	-		49	51	53	55	57	59	61	64	67	70	73				<u></u>	
	Service of earlier		NPSH = n		-	lines.					2,4	2,5	2,6	2,7	2,8	2,9	3	3,4	3,9	4,5	5,2	47	4-	-		
	1	c		н															72	71 48	69	67	65	63	57	50
			-	P		-	-			-	-							-	46 83	48 82	50 80	52 78	54 76	56	58 70	65
		1		н															54		59	62	65	74 67	1000000 C	74
	100-250/4	В	н		1	-	-	-			1 3	-		1		-	-		93	56,5 92	91	90	89	87	70,5 82	77
	100x250/1	В	н	P	1			10			1 1								60	63	66	69	72	75	81	87
	100x250/1	В	н	H										0.000				-		0.3	00	07	14	13	01	
	100x250/1	۸		Р						2				27,-5						41		4.0		6.7	4	
001	100x250/1	۸	H NPSH = r	P												-			4,5	4,6	4,7	4,9	5,1	5,3	6	_
x 100	100x250/1	۸		rt H															101	98	95	91	86	80	69	55
20 x 100	100x250/1	۸		H P															101 64	98 66	95 68	91 69,5	86 71	80 72	69 74	55 76
150 x 100	100x250/1	۸		H P															101 64 112	98 66 110	95 68 106	91 69,5 102	86 71 98	80 72 92	69 74 81	53 76 67
150 x 100		A D		H P H															101 64 112 72	98 66 110 74	95 68 106 76	91 69,5 102 78	86 71 98 80	80 72 92 82	69 74 81 84	55 76 67 86
150 x 100	100x250/1	A D	NPSH = n	H P															101 64 112 72 123	98 66 110 74 121	95 68 106 76 117	91 69,5 102 78 113	86 71 98 80 109	80 72 92 82 104	69 74 81 84 94	55 76 67 86 82
150 x 100		A D C	NPSH = n	H P															101 64 112 72 123 80	98 66 110 74 121 82,5	95 68 106 76 117 85,5	91 69,5 102 78 113 88,5	86 71 98 80 109 92	80 72 92 82 104 94	69 74 81 84 94 97,5	76 67 86 82 101
150 x 100		A D C	NPSH = n	H P H															101 64 112 72 123	98 66 110 74 121	95 68 106 76 117	91 69,5 102 78 113	86 71 98 80 109	80 72 92 82 104	69 74 81 84 94	55 76 67 86 82

TOLLERANZE:
TOLERANCES: UNI/ISO 2548 Cl. C annex.
TOLERANCES:

RAPPORTO TIPO RATIO TYPE RAPPORT TYPE	RAPPORTO RATIO RAPPORT	N° DENTI TOOTH N° DENTS N°	P.d.F G/1' P.T.O RPM P.d.F T/1'	POMPA - G/1' PUMP - RPM POMPE - T/1'
н	5,27	79/15		2870
ĸ	5,71	80/14		3090
x	6,25	81/13	540	3380
Y	6,83	82/12		3690
z	7,54	83/11		4070

### Biraghi Pompe 1906 Plants







NIGERIA UAE

ITALY



### **HEADQUATERS:**

Via della Giardina 11, Monza, 20900

#### **Contacts:**

+39 02-89680866

in fo@biraghipompe 1906. it

Copyright ® 2018 Biraghi Pompe 1906 All Rights Reserved